

GENERAL INSTRUCTIONS TO BE OBSERVED IN PREPARATION
OF SHIPMENT REQUEST FORM
FOR USE WHEN REQUESTING SHIPPING SERVICES
(Not otherwise covered by Sales Order Instruction 1200)

SOLE TO: **Commanding Officer
Headquarters Detachment
Bolling Air Force Base
Washington, D.C.**

SHIP TO: **Electronic Test Division
Naval Air Test Center
Patuxent, River, Maryland**

ATTN: **[REDACTED]**

Originator's reference No. _____
Date **9/23/58**

MIC. SIZE _____
Pack per 1000 _____
Material **6146-1**
Charge & Labor **6053-1**
Authority for Shipment _____
Value for Insurance Purposes **\$75.00**

FOIAB3A

REASON FOR SHIPMENT: _____

ACCOUNT TO BE CHARGED **See Above**
CHARGE NUMBER TO BE CREDITED _____

ITEM NO.	MODEL OR PART NO.	DESCRIPTION	QUANTITY
140	180-10-1245	Resistor	2
323	120-51-2215	Resistor	2
384	146-105-1	Transformer	2
50. 21100			

Special Marking and/or Shipping Instructions _____

Requested Shipping Date **As soon as possible.**

Equipment to be shipped is property of: Agency **Air Force** (AF: Navy, etc.)

Is shipment to be made on a "F.O.B." basis? **No** If so, date of receipt _____

and applicable RMA No. _____

Prepaid **X**
SHIP: Collect _____
C. O. D. _____

Does shipping authority prescribe use of Government bill of lading? **No**

INVOICE INSTRUCTIONS: No Charge _____
Direct Charge _____
Clear Charge (for "clean" shipments only) _____

10-17-58

APPROVED BY: _____

FOIAB3A